



MicPre 5.0 Mix Link Cable Wiring Diagram


For linking two MP 5.0's

MP50-LINK2 (Shown)




MicPre 5.0 Mix Link Cable Wiring Diagram

For linking two or more MP 5.0's





MP50-LINK4 (Shown)
MP50-LINK6
MP50-LINK8
MP50-LINK12
MP50-LINK16



MicPre 5.0 Mix Link Cable Wiring Diagram

M-S cable wiring diagram

MP50-MS



~or~

